



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
NEWFIELD GREEN ROAD	o/s 8	TR: Felling: Senescent	Senescent - poor physiological condition	Prunus sp	Plant in verge o/s 8, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 12	TR: Felling: Decay	Scaffold decayed, structural integrity in doubt	Prunus sp	Plant in verge o/s 12, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 16	TR: Felling: Structural Integrity	Extensive stem gumosis, poor specimen	Prunus sp	Plant in verge between 16 to 18, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 50	TR: Felling: Structural Integrity	Substantial decay of scaffold limb, poor structural condition	Prunus sp	Plant in verge o/s 50, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 52	TR: Felling: Structural Integrity	Stem and scaffold branch decaying	Prunus sp	Plant in verge o/s 52, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 56	TR: Felling: Structural Integrity	Stem gumosis and decay of scaffold	Prunus sp	Plant in verge o/s 56, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 6	TR: Felling	Lateral root uplifting f/w	Prunus sp	Plant in verge between 4 to 6, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 33	TR: Felling	Shallow rooting damaging f/w and potential 3rd party driveway claim	Prunus sp	Plant in verge o/s 33, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 35 to 37	TR: Felling	Shallow rooting damaging, recent patch repair uplifting	Prunus sp	Plant in verge o/s- between 35 to 37, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 62	TR: Felling	F/W disrupted by shallow rooting	Prunus sp	Plant in verge o/s- between 60 to 62, (same as old tree)	Malus 'Evereste'
NEWFIELD GREEN ROAD	o/s 31	TR: Felling	Basal bark damage, f/w obstructed by leaning stem	Prunus sp	Plant in verge o/s 31 (same as felled tree)	Malus 'Evereste'